

From: Colin Molyneux
Sent: 15 November 2016 14:56
To: maryemws@gmail.com
Cc: Alison Molyneux
Subject: RE: Bend at bottom of Manse Hill

Mary

Thanks for this and taking up the cause.

There appears to be more than one spring, dependent upon the weather as well as an inclination for black ice to form on the bend that is not a result of the water on the hill.

As you all probably travel down this stretch I need not describe the mess that we are loth to clear up when the leaves finally come off, given that one can guarantee another few incidents this winter. There was a few years ago a complete high hedge round all the corner but we have taken out several sections as events have occurred and it is tempting to take out the rest. Leaving a drop of 6 plus feet down to the meadow and the expectation of more serious incidents.

I think our choices would;

1. Big Chevrons and markings on the road
2. No point in extending any speed signs.
3. Replace temporary cones with permanent bollards with night markings and reflectors.
4. We have a pile of timber posts that can sit in the verge if someone would install them but neither these nor bollards will stop vehicles, they will only warn along with anything else available.

Thank you for your support

Colin Molyneux
07968176670